

Photographic record of The Mayfair Ballroom and Mayfair site in context



Aerial View of Site (outlined in red) and Local Context







Contextual context of building with car park to front





View of south elevation showing double pitched roof.



View of car park to South side of building in context





External canopy which is not coeval to the structure



Asbestos roof of main structure. St Canice's Cathedral to rear. And city wall to rear







The city wall and Breagagh River adjacent to car park





The south elevation of the dance hall showing the extended outdoor terrace which is not coeval to the building. The pitched roof is asbestos. The city wall is visible to the rear



Existing site context showing car park







Interior showing doors and ceiling tiles not coeval to the dance hall structure





Interior photo showing form of trusses of the smaller pitch roof .The ceiling tiles are not coeval to the structure










Interior photo showing former dance hall. The large trussed roof cannot be viewed due to ceiling tiles







Interior of office showing ceiling tiles and doors which are not coeval to the original structure








Interior of office showing ceiling tiles and doors which are not coeval to the original structure





Interior of office showing ceiling tiles and doors which are









Detail of existing concrete wall and window connection. There is no insulation or cavity the wall is constructed of concrete block





Service Yard to West of Existing Building detail of city wall to right of photo



Service Yard to West of Existing Building detail of concrete wall and concrete steps

